



State of New Hampshire
DEPARTMENT OF ENVIRONMENTAL SERVICES

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095
(603) 271-3406 FAX (603) 271-7894



December 4, 2002

Mr. Robert Beaurivage
Manchester Water Works
281 Lincoln Street
Manchester, NH 03101

Re: Letter of Deficiency (LOD), Dated June 12, 2002
Clark Pond East Dam #013.03 and Clark Pond West Dam #013.04 - Auburn

Dear Mr. Beaurivage:

Based on a follow-up inspection made to the above referenced dam on November 27, 2002, the Department of Environmental Services (DES) has determined that the deficiencies noted in the above referenced LODs have been corrected. The next routine inspection of both dams is scheduled for the 2007 inspection season.

DES would like to commend you on the work done relative to Clark Pond East and West Dam. A lot of work has been done to these dams, including an outstanding effort to bring the earthen embankment flush with the concrete abutments, to cut and remove all brush on the dam, and to re-grade and seed the downstream face of the left embankment. DES appreciates your maintenance efforts and the quality of work that has been done to this dam.

If you have any questions or comments, please contact me at 271-3406 or write to the Water Division at the address listed above.

Sincerely,

COPY
Amy C. Clark
Amy C. Clark, P.E.
Dam Safety Engineer

cc: Gretchen Rule✓
ACC/was/h:/safety/wendy/ltr/1303&1304ltr.doc